NORTHWEST CORNER OF SECTION 19, T-28-N.

R-16-E I.M. FOUND AND ACCEPTED A 1/2" IRON

PIN INSIDE OF A 2" PIPE AND ONE REFERENCE

LISTED ON A CERTIFIED CORNER RECORD FILED

BY GUY R. BUCKLAND OF BUCKLAND SURVEYING COMPANY, INC. ON MARCH 20, 2007. SET TWO

WEST QUARTER CORNER OF SECTION 19, T-28-N, R-16-E, I.M. FOUND AND ACCEPTED A 1/2" IRON PIN WITH YELLOW CAP AND THREE REFERENCES LISTED ON A CERTIFIED CORNER RECORED FILED

BY GUY R. BUCKLAND OF BUCKLAND SURVEYING

SOUTHWEST CORNER OF SECTION 19, T-28-N,

THREE REFERENCES LISTED ON A CERTIFIED

R-16-E, I.M. FOUND AND ACCEPTED A 2" PIPE AND

CORNER RECORD FILED BY GUY R. BUCKLAND OF BUCKLAND SURVEYING COMPANY, INC. ON MARCH

NE face 8*./ steel corner post

COMPANY, INC. ON MARCH 20, 2007. THIS POSITION WAS RECORDED AS LOST.

REFERENCES.

FED. ROAD	STATE	PROJ. NO.	FISCAL	SHEET	TOTAL
DIST. NO.	SIMIC	PROOF NO.	YEAR	NO.	SHEETS
8	OKLA.	24750(04)		47	127
DESCRIPTION	N .	REVISION	s		DATE

NORTH QUARTER CORNER OF SECTION 19, T-28-N, R-16-E 1.M. FOUND AND ACCEPTED A 1/2" IRON ROD AND 3 REFERENCES AS LISTED ON A CERTIFIED CORNER RECORD FILED BY GUY R. BUCKLAND, LS 1323, OF BUCKLAND SURVEYING COMPANY, INC. ON NOVEMBER 5, 2008. SET ONE REFERENCE.

| \(\int \footnote{60} \) nall in SW face of | \(\int \footnote{60} \) locust tree 40d nail in power pole 42.40°-N 63.31°W 78.8' N 47°26' W 2635.06' 9016 9018 2582.97" 5/8" Iron Rod EW-8 N 88'31'46J4" 88'32'22.05" E (9019) 5/8" Iron Pi Gravel <u>Gravel</u> 262 1262.77 N 5r40 E 9017 43.77'-S 5422'W 3 32.4° 5 48°22' W -51.35' S 28'24' E S 1508 W 2.8' S 87°44' E 40d nall In-NE face of PP NW 2" steel corner post of gas valve fence 1/2" Iron pin in 5 21'06' E 40d nall in-power pale 40d nall in 6° wood corner post GOV LOT 1 9022) _{1266.52}, 9023) S 88^36'51.10" W GOV LOT 2 55.42 N 09'23' W /18.72' N 28^20' E N 20 20 3/8" Iron Pin (9027)-(9024) 1270.28, 9025 (19) 13.68° S 45°23′ W N 88°41′19.16″ E 2592.45′ 60d nail in 10" Oak COMPUTED ONLY 5 72⁴² L15.43' S 83^51' E GOV LOT 3 1274.12 9031 S 88^42'27.46" W 9030 GOV LOT 4 60d nali in 12* Hockberry face of brace pole 47.2 N 4232 W /-3/4° Iron Pin In 2° Pipe (9035)--1/2" Iron Pln r Bolt N 8835' E 53' SO 1/2' Iron Pin ,(9033) (9032)_{1277.96}' 9034 60d nall In 8 8836'13.85" W 2636.39' 3 S 88 43 35.51" W ^15.0° S 09°29′W 2" Pipe 3/8" Iron Pin-2602.28' S 33 22 W /

NORTHEAST CORNER OF SECTION 19, T-28-N, R-16-E I.M. FOUND AND ACCEPTED A 58" IRON PIN AND 4 REFERENCES LISTED ON A CERTIFIED CORNER RECORD FILED BY GUY R. BUCKLAND OF BUCKLAND SURVEYING COMPANY, INC. ON NOVEMBER 5, 2008.

EAST QUARTER CORNER OF SECTION 19, T-28-N, R-16-E, I.M. FOUND AND ACCEPTED A 3/8" IRON PIN SET BY PERSONS UNKNOWN, SET THREE REFERENCES.

NOTE: REFERENCE'S SHOWN ARE NOT TO SCALE

SOUTHEAST CORNER OF SECTION 19, T-18-N, R-16-E, I.M. FOUND AND ACCEPTED A 3/4" IRON PIN IN A 2" PIPE AND TWO REFERENCES SET BY PERSONS UNKNOWN. SET TWO REFERENCES.

SOUTH QUARTER CORNER OF SECTION 19, T-28-N, R-16-E, I.M. FOUND AND ACCEPTED A 1" SQUARE BOLT SET BY PERSONS UNKNOWN, SET TWO REFERENCES.

PLS	DMM	OKLAHOMA DEPARTMENT OF TRANSPORTATION SURVEY DIVISION
DRAWN	ARR	
CHECKED	VKM	SURVEY DATA SHEET (13)
APPROVED	DMM	
CREW	GES, INC	SWO 4721(1) PROJECT NO. 24750(04) SHEET NO. 47