

FED. ROAD DIST. NO.	STATE	PROJ. NO.	FISCAL YEAR	SHEET NO.	TOTAL SHEETS
	OKLA.				

DESCRIPTION	REVISIONS	DATE

HISTORICAL LETTER AND WRITTEN REPORT  
SWO 4600(1)-J/P17671(34)-U.S. 270 - Dewey County

- 42. S/4 Corner of Section 9 - Set a #4 bar with "CA 2054" cap. Location was re-established using existing highway plans. No OCCR was on file for this location.
- 43. SE Corner of Section 9 - Found and accepted a #4 bar with "CA 980" cap. Location is in agreement with OCCR filed in 2010 and is in harmony with existing improvements. The reference monuments were found and verified.
- 44. N/4 Corner of Section 15 - Found and accepted a #4 bar with "CA 980" cap. Location is in agreement with OCCR filed in 2004 and is in harmony with existing improvements. The reference monuments were found and verified.
- 45. NE Corner of Section 15 - Found and accepted a bent #4 bar with "CA 980" cap. Location is in agreement with OCCR filed in 2010 and is in harmony with existing improvements. The reference monuments were found and verified.
- 46. W/4 Corner of Section 16 - Found and accepted a #4 bar with an unreadable cap. Location is in agreement with OCCR filed in 1988 and is in harmony with existing improvements. One of the reference monuments were found and verified.
- 47. Center of Section 16 - Computed only.
- 48. E/4 Corner of Section 16 - Found and accepted a #4 bar with "CA 980" cap. Location is in agreement with OCCR filed in 2004 and is in harmony with existing improvements. The reference monuments were found and verified.
- 49. Center of Section 15 - Computed only.
- 50. E/4 Corner of Section 15 - Found and accepted a #4 bar with "CA 980" cap. Location is in agreement with OCCR filed in 2004 and is in line with east west fence. The reference monuments were found and verified.
- 51. SW Corner of Section 16 - Found and accepted a #4 bar. Location is in agreement with OCCR filed in 2010 and is in harmony with existing improvements. Two of the reference monuments were found and verified.
- 52. S/4 Corner of Section 16 - Set a #4 Bar with "CA 2054" Cap for corner. Location was re-established by using existing fence lines running north south and 33 feet south of fence corner post. No OCCR was on file for this location.
- 53. SE Corner of Section 16 - Found and accepted a #4 bar with "CA 980" cap. Location is in agreement with OCCR filed in 2004 and is in harmony with existing improvements. Three of the reference monuments were found and verified.
- 54. S/4 Corner of Section 15 - Found and accepted a #4 bar with "CA 980" cap. Location is in agreement with OCCR filed in 2004

HISTORICAL LETTER AND WRITTEN REPORT  
SWO 4600(1)-J/P17671(34)-U.S. 270 - Dewey County

- and is in harmony with existing improvements. Two of the reference monuments were found and verified.
- 55. SE Corner of Section 15 - Found and accepted a #4 bar. Location is in agreement with OCCR filed in 2010. The reference monuments were found and verified. Location seems to be in harmony with surrounding improvements. The monument referenced in OCCR filed in 2004 was not found.
- 56. N/4 Corner of Section 23 - Found and accepted a #4 bar with "1737 OK" cap. Location is in agreement with OCCR filed in 2010. The reference monuments were found and verified.
- 57. NE Corner of Section 23 - Found and accepted a #4 bar. Location is in agreement with OCCR filed in 2010 and is in harmony with existing improvements. Two of the reference monuments were found and verified.
- 58. W/4 Corner of Section 22 - Found and accepted a #4 bar with cap. Location is in agreement with OCCR filed in 2001 and is in harmony with existing improvements. Two of the reference monuments were found and verified.
- 59. Center of Section 22 - Computed only.
- 60. E/4 Corner of Section 22 - Found and accepted #5 bar. Location is in agreement with OCCR filed in 2001 and is in harmony with existing improvements. Three of the references were found and verified. Also found a #4 Bar with "1737 OK" cap referenced in OCCR filed in 2010 but did not accept this location because of the method in which it was set and it did not fit surrounding improvements.
- 61. Center of Section 23 - Computed only.
- 62. E/4 Corner of Section 23 - Found and accepted a #4 bar with "1737 OK" cap. Location is in agreement with OCCR filed in 2010 and is in harmony with existing improvements. The reference monuments were found and verified.
- 63. SW Corner of Section 22 - Found and accepted a #3 bar with "PLS 864" cap. Location is in agreement with OCCR filed in 2010 and 2000 and is in harmony with existing improvements. The reference monuments were found and verified.
- 64. S/4 Corner of Section 22 - Found and accepted a #3 bar. Location is in agreement with OCCR filed in 2010 and 2000 and is in harmony with existing improvements. The reference monuments were found and verified.
- 65. SE Corner of Section 22 - Set a #4 bar with "CA 2054" cap for corner. Location was re-established by using existing highway plans and splitting fences running east west. Also found a #4 Bar with "CA 980" cap referenced in OCCR filed in 2004 but did not

HISTORICAL LETTER AND WRITTEN REPORT  
SWO 4600(1)-J/P17671(34)-U.S. 270 - Dewey County

- accept this location because it did not fit existing highway plans.
- 66. S/4 Corner of Section 23 - Found and accepted a 60D nail in the top center of an 8" fence corner post. Location is in agreement with existing intersection of fence lines. Also found a #4 bar with "1737 OK" cap referenced in OCCR filed in 2010 but did not accept this location because the method in which it was set and it did not fit surrounding improvements.
- 67. SE Corner of Section 23 - Set a #4 bar with "CA 2054" cap for corner. Location was re-established by splitting fences running north south. Also found a #4 bar with "PLS 1587" cap but did not accept this location because it did not fit surrounding improvements. No OCCR was on file for this location.
- 68. W/4 Corner of Section 27 - Found and accepted a #4 bar. Location is in agreement with existing improvements. No OCCR was on file for this location.
- 69. Center of Section 27 - Computed only.
- 70. E/4 Corner of Section 27 - Set a #4 bar with "CA 2054" cap for corner. Location was re-established using a fence line running east west. Also found a #4 bar with "1737 OK" cap referenced in OCCR filed in 2010 but did not accept this location because the method in which it was set and it did not fit surrounding improvements.
- 71. Center of Section 26 - Computed only.
- 72. E/4 Corner of Section 26 - Found and accepted a 60D nail. Location is in agreement with existing improvements. Also found a #4 bar with "1737 OK" cap referenced in OCCR filed in 2010 but did not accept this location because the method in which it was set and it did not fit surrounding improvements.
- 73. SW Corner of Section 27 - Set a #4 bar with "CA 2054" cap for corner. Location was re-established to be in agreement with existing improvements. No OCCR was on file for this location.
- 74. S/4 Corner of Section 27 - Found and accepted a bent 60D nail. Location is in agreement with existing improvements. No OCCR was on file for this location.
- 75. SE Corner of Section 27 - Set a #4 bar with "CA 2054" cap for corner. Location was re-established by splitting fence lines running east west. Also found a #4 bar with a "PLS 1587" cap but did not accept this location because it did not fit surrounding improvements. No OCCR was on file for this location.
- 76. S/4 Corner of Section 26 - Set a #4 bar with "CA 2054" cap for corner. Location was re-established by splitting fence lines running east west and in line with fence line running north. Also found a #4 bar with "PLS JF WATSON" cap referenced in OCCR

PLS	KH		OKLAHOMA DEPARTMENT OF TRANSPORTATION SURVEY DIVISION
DRAWN	CF,SK		
CHECKED	SS		
APPROVED	KH		
CREW	JH,SA,BH,DR		
			<b>SURVEY DATA SHEET</b>
			SWO 4600 (1) PROJECT NO. 17671(34) SHEET NO. 34