

SWO 4864(1) - SH 58 - Caddo County
 Historical Letter & Written Report
 Page 13 of 21

Section 16, Township 10 North, Range 13 West, 1.M. - Continued;

South Quarter Corner;

Found existing local evidence, fences and such. Set a #4 Rebar with Cap flush with the surface on line between section corners and in line with north-south quarter line fence. Said point is approximately 31' south and parallel in the east-west fence, being the north section line 16'W, along the south line of the southwest quarter of Section 16. The south line of Section 16 is closed. The corner as established appears to agree with local evidence and evidence of occupation has viewed from 2010 NAIP Imagery. I assigned said corner ODOT Monument No. C-8-1208.

West Quarter Corner;

Found existing local evidence, fences and such. Set a #4 Rebar with Cap 0.5' below the surface of the gravel road proportionately between fence corners. The distance between corners is 86.1'. Split between fence corners lands in the middle of the existing roadway. Corner as established appears to agree with local evidence and evidence of occupation has viewed from 2010 NAIP Imagery. I assigned said corner ODOT Monument No. C-8-1209.

Section 21, Township 10 North, Range 13 West, 1.M.

Southwest Corner;

Found existing local evidence, fences and such. The east-west position of corner was established in the approximate center of the north-south section line roads, within a couple of feet of the 1901 GLO distance east and west to local evidence. The north-south position was established in the approximate center of the east-west section line roads, within a couple of feet of the 1901 GLO distance north and south to the one quarter corners. Therefore I set a #4 Rebar with Cap 0.5' below the surface of the road for said corner and assigned it ODOT Monument No. C-8-1210.

South Quarter Corner;

Found existing local evidence, fences and such. Set a #4 Rebar with Cap 0.5' below the surface of the gravel road proportionately between Section Corners. Said point is one foot east and 32.5' south of existing fence corner to north. This point is also approximately 33.7 feet north of the end of the irrigation sprinkler to south. Corner as established appears to agree with local evidence and evidence of occupation has viewed from 2010 NAIP Imagery. I accepted said position assigned said corner ODOT Monument No. C-8-1211.

West Quarter Corner;

Found existing local evidence, fences and such. Set a #4 Rebar with Cap 0.5' below the surface of the gravel road on line between section corners and in line with old lone post to west delineating east-west one quarter section line and divisions in fields. Corner as established appears to agree with local evidence and evidence of occupation has viewed from 2010 NAIP Imagery. I assigned said corner ODOT Monument No. C-8-1212.

SWO 4864(1) - SH 58 - Caddo County
 Historical Letter & Written Report
 Page 14 of 21

Section 22, Township 10 North, Range 13 West, 1.M.

Southwest Corner;

Found a PK Nail flush with the surface of the asphalt and two of the references per CCR by Randy Mosley, PLS 1082, dated January 31, 1990 and two of the references per CCR by Miles M. Wood, PLS 1384, dated June 30, 2003. He states that he found a PK Nail in location of Spike as per PLS 1082. According to ODOT SAP No. 775(2) Part 1 Plans dated 1951 and SWO 1704(1) Project SAP 775(2), Caddo County, SH 58 Field Book there were references marked in the headwalls of the side drain west of the intersection. The plans and field book denote that this structure had 45° wings, but the structure in place has 90° headwalls. The "X"s found in said headwalls are in the area indicated on said plans and as denoted in said field book. Both references are within 0.7' and the computed position, based on said references, if accepted, would be 0.1' South and 0.7' west of found Monument which closely agrees with said references per recorded CCR's. Being no more different than described, I accepted PK Nail for corner and assigned it ODOT Monument No. C-8-1213.

South Quarter Corner;

Found a #4 Rebar 0.7' Deep and two of the references per CCR by Randy Mosley, PLS 1082, dated January 31, 1990 and two of the references per CCR by Miles M. Wood, PLS 1384, dated June 30, 2003. Mr. Wood states that he found #4 Rebar as per PLS 1082. Monument found closely agrees with said references. I therefore accepted #4 Rebar for corner and assigned it ODOT Monument No. C-8-1214.

West Quarter Corner;

Found fences, structures, assorted references and centerline control for SH58. I reestablished the centerline according to SAP No. 775(2) SH58 Plans, dated 1951 and ODOT SWO1704 Survey, Caddo County for SH58. Survey Completed February 2, 1951. Therefore I set a MAG Nail with washer according to said plans and surveys. Said monument agrees with the local evidence. therefore I accepted the monument for the corner and assigned it ODOT Monument No. C-8-1215.

Section 23, Township 10 North, Range 13 West, 1.M.

Southwest Corner;

Found a Bent #4 Rebar 1.0' Deep and two of the references per CCR by Bill J. Casey, PLS 1122, dated March 12, 1981, two references by Randy Mosley, PLS 1082, dated January 31, 1990. Mr. Mosley states that he found #3 Rebar and set #4 Rebar on top of #3. Also found all of the references per CCR by Miles M. Wood, PLS 1384, dated June 30, 2003. Mr. Wood states that he also found two nails in intersection, but set #3 Rebar, but does not explain how he determined its location. Also found three of the references per CCR by Ronald Campo, PLS 1462, he states that he set #4 Rebar with Cap 6" below surface in location previously filled by Bill Casey, PLS

SWO 4864(1) - SH 58 - Caddo County
 Historical Letter & Written Report
 Page 15 of 21

Southwest Corner - Continued;

1122. I believe that two of each of the CCR's files of record are the same. All are similar except for Mr. Woods. His references would put his point approximately three feet west. I could not find another monument at this point. Therefore I straightened and reset the Bent #4 Rebar found and assigned it ODOT Monument No. C-8-1216.

West Quarter Corner;

Found one of the references per CCR by Bill J. Casey, PLS 1122, dated March 12, 1981. I computed a point equal distance and on line between section corners as described by Mr. Casey in his CCR, but there was about a 16 foot discrepancy and it appeared he was using the Original (GLO) Notes of 1874. I could not find the monument called for. Therefore I set a #4 Rebar with Cap 0.5' deep, not equal distance but proportioned according to the GLO Survey of 1901. I accepted the #4 Rebar for corner and assigned it ODOT Monument No. C-8-1217.

Section 26, Township 10 North, Range 13 West, 1.M.

Southwest Corner;

Found a #4 Rebar 0.2' below the surface of the asphalt and two of the references per CCR by Bill J. Casey, PLS 1122, dated September 30, 1982, found all of the references per CCR by Phillip Stevenson, PLS 1159, dated September 13, 1994 and all the references per CCR by Miles M. Wood, PLS 1384, dated June 30, 2003. Monument found closely agrees with said references. I therefore accepted #4 Rebar for corner and assigned it ODOT Monument No. C-8-1218.

West Quarter Corner;

Found a 60d Nail 0.2' deep east of existing roadway, believe to be a random traverse point. Set a #4 Rebar with Cap 0.5' below the surface of the gravel road proportionately between fence corners. The distance between corners is 65.8'. Corner as established appears to agree with local evidence and evidence of occupation has viewed from 2010 NAIP Imagery. I assigned said corner ODOT Monument No. C-8-1219.

Section 27, Township 10 North, Range 13 West, 1.M.

Southwest Corner;

Found a PK Nail on the surface of the asphalt and three of the references per CCR by Randy Mosley, PLS 1082, dated March 31, 1990. He states that he found a PK Nail and replaced it with a large spike. The PK Nail found closely fits his recorded references. Also found a reference, an "X" on top of a headwall, taken from the field book for ODOT SWO1704(1) Survey, Project SAP775(2), completed in February 2, 1951 at Station 71153.8. also refers to WPA Plans 7-84A dated 1919. Could not find the corresponding "X" on the other headwall, but if the one "X" found is per the above information, it appears that said monument found would be within less than 1.0