


NOTE:
ALL SPLICING SHALL BE DONE IN THE FIRST PEDESTAL WIRED,
NO SPLICES SHALL BE MADE IN SECOND PEDESTAL.



WIRING CONNECTIONS
IN E/W
PEDESTAL POLE BASE

WIRING CONNECTIONS
IN N/S
PEDESTAL POLE BASE

BEFORE YOU DIG CALL OKIE 811

10816 EXECUTIVE CENTER DR. STE. 300 LITTLE ROCK, ARKANSAS 72211

	DESIG	N BLV		OKLAHOMA I		OF TRANS	<b>PORTATION</b>	
	DRAW	N JAB			DESIGN D	IVIOION		
	DRAWI	N JAB						
	CHECKE	ED BLV		DOWNTOWN PEDESTAL WIRING DETAIL				
	CHECK	ED BLV						
	400000			1	STD. (	311B		
	APPROV	ED BLV						
_			· .			708(06)		E 4
	SQUAD	) <b> </b> Ja	acobs	PROJECT	NO. 23	700(00)	SHEET NO.	51