


ALL CABLE MUST BE RUN THRU GUSSETED TUBE AND ENCLOSED SHOES.

NO HOLES DRILLED IN SIGNAL HEAD FACTORY MOUNTING HOLES USED ONLY USE OPTICOM CABLE OR AN APPROVED EQUAL.


5-SECTION LEFT TURN CLUSTER



ALL CABLE MUST BE RUN THRU GUSSETED TUBE AND ENCLOSED SHOES.

NO HOLES DRILLED IN SIGNAL HEAD FACTORY MOUNTING HOLES USED ONLY USE OPTICOM CABLE OR AN APPROVED EQUAL.

5-SECTION RIGHT TURN CLUSTER



NO HOLES DRILLED IN SIGNAL HEAD FACTORY MOUNTING HOLES USED ONLY USE OPTICOM CABLE OR AN APPROVED EQUAL.

3-SECTION SIGNAL HEAD

BEFORE YOU DIG
CALL OKIE
811



JACOBS

10816 EXECUTIVE CENTER DR. STE. 300
LITTLE ROCK, ARKANSAS 72211

| | | |
|----------|--------|------------------------------------------------------------------|
| DESIGN | BLV | OKLAHOMA DEPARTMENT OF TRANSPORTATION DESIGN DIVISION |
| DRAWN | JAB | |
| CHECKED | BLV | |
| APPROVED | BLV | |
| SQUAD | Jacobs | |

SIGNAL HEAD WIRING **STD. 614B**

PROJECT NO. 23708(06) SHEET NO. 54