

FED. ROAD DIST. NO.	STATE	PROJ. NO.	FISCAL YEAR	SHEET NO.	TOTAL SHEETS
	OKLA.				

DESCRIPTION	REVISIONS	DATE

HISTORICAL LETTER AND WRITTEN REPORT
SWO 4600(1)-J/P17671(34)-U.S. 270 - Dewey County

4. N/4 Corner of Section 31 - Found and accepted a #4 Bar with cap stamped "1737 OK" using OCCR filed in 2010. The reference monuments were also found and verified. Could not find the monument or its references for the OCCR filed in 1985.
5. NE Corner of Section 31 - Set a #4 Bar with "CA 2054" Cap using references in the OCCR's filed in 2010 and 2002.
6. W/4 Corner of Section 36 - Found and accepted a #4 bar using OCCRs filed in 2009 and 1986. The reference monuments were also found and verified.
7. Center of Section 36 - Computed Only
8. E/4 Corner of Section 36 - Set a #4 Bar with "CA 2054" Cap for corner. Re-established location by using existing highway plans and local improvements. Location appears to be in harmony with surrounding improvements.
9. Center of Section 31 - Computed only
10. E/4 Corner of Section 31 - Found and accepted a #4 Bar set in line with fence lines running east and west. No OCCR were filed for this location.
11. SW Corner of Section 36 - Found and accepted a #3 Bar. Location is in agreement with OCCR filed in 1986. The reference monuments were found and verified.
12. S/4 Corner of Section 36 - Set a #4 Bar with "CA 2054" Cap for corner. Location was re-established using an existing fence line running east west and at equidistant for section corners. No OCCR was on file for this location.
13. SE Corner of Section 36 - Set a #4 Bar with "CA 2054" Cap for corner. Location was re-established using and existing fence line running east west and equidistant between found monument at southwest corner and existing improvements around the southeast corner. Also found a #4 bar with "CA 794" cap but did not accept because it was not in agreement with existing improvements. No OCCR was on file for this location.
14. N/4 Corner Section 6 - Set a #4 Bar with "CA 2054" Cap for corner. Location was re-established using existing fence lines running east, west, north, and South. Also used existing highway plans. Also found a #4 Bar with "SRA 794" Cap at a point being equidistant and online with opposing section corners. Did not accept this location because of the method used to set it and it did not fit surrounding improvements. No OCCR was on file for this location.
15. NE Corner Section 6 - Found and accepted a #4 Bar. Location is in agreement with OCCR filed in 2010, 1996, and 1979. The reference monuments were found and verified.

HISTORICAL LETTER AND WRITTEN REPORT
SWO 4600(1)-J/P17671(34)-U.S. 270 - Dewey County

16. N/4 Corner of Section 5 - Set a #4 Bar with "CA 2054" Cap for corner. Location was re-established by using existing fence lines running north south and online between opposing section corners. No OCCR was on file for this location.
17. NE Corner of Section 5 - Found and accepted a #4 Bar with "CA 980" Cap. Location is in agreement with OCCR filed in 2004. The reference monuments were found and verified.
18. N/4 Corner of Section 4 - Set a #4 Bar with "CA 2054" Cap for corner. Location was re-established by using existing fence lines running north south and equidistant between fence corner posts. Also found a #4 Bar from OCCR filed in 2010. Did not agree with this location because of the method used to set it and did not fit the surrounding improvements.
19. NE Corner of Section 4 - Found and accepted a #4 Bar. Location is in agreement with OCCR filed in 2010 and is in harmony with surrounding improvements. The reference monuments were found and verified.
20. W/4 Corner of Section 6 - Set a #4 Bar with "CA 2054" Cap for corner. Location was re-established by using existing fence lines running east west and 33 feet west of fence corner post. No OCCR was on file for this location.
21. Center of Section 6 - Computed only.
22. E/4 Corner of Section 6 - Found and accepted a #3 bar. Location is in agreement with OCCR filed in 1979. One reference monument was found and verified.
23. Center of Section 5 - Computed only.
24. E/4 Corner of Section 5 - Found bent #4 bar. Location is in agreement with OCCR filed in 2010. The reference monuments were found and verified. Location seems to be in harmony with the surrounding improvements. The monument referenced in OCCR filed in 2004 was not found.
25. Center of Section 4 - Computed only.
26. E/4 Corner of Section 4 - Found and accepted a #4 bar. Location is in agreement with OCCR filed in 2010. The reference monuments were found and verified.
27. SW Corner of Section 6 - Found and accepted a bent #4 bar. Location is in agreement with OCCR filed in 1992. The reference monuments were found and verified.
28. S/4 Corner of Section 6 - Found and accepted a 1" metal bar. Location is in harmony with existing improvements. No OCCR was on file for this location.

HISTORICAL LETTER AND WRITTEN REPORT
SWO 4600(1)-J/P17671(34)-U.S. 270 - Dewey County

29. SE Corner of Section 6 - Found and accepted a #4 bar. Location is in agreement with OCCR filed in 2010 and is in harmony with existing improvements. The reference monuments were found and verified.
30. S/4 Corner of Section 5 - Found and accepted a #4 bar. Location is in agreement with OCCR filed in 2004 and is in harmony with existing improvements. The reference monuments were found and verified.
31. SE Corner of Section 5 - Found and accepted a magnetic nail. Location is in agreement with OCCR filed in 2010 and 2004 and is in harmony with existing improvements. Some of the reference monuments were found and verified.
32. S/4 Corner of Section 4 - Set a #4 bar with "CA 2054" cap. Location was re-established using existing highway plans. Could not find the monument referenced in OCCR filed in 2010. The reference monuments were found, but did not reference a common location.
33. SE Corner of Section 4 - Found and accepted a #4 bar. Location is in agreement with OCCR filed in 2010 and is in harmony with existing improvements. The reference monuments were found and verified.
34. W/4 Corner of Section 8 - Found and accepted a #4 bar. No OCCR were filed for this location.
35. Center of Section 8 - Computed only.
36. E/4 Corner of Section 8 - Found and accepted a #4 bar. Location is in harmony with existing improvements. No OCCR was on file for this location.
37. Center of Section 9 - Computed only.
38. E/4 Corner of Section 9 - Found and accepted a #3 bar. No OCCR were filed for this location.
39. SW Corner of Section 8 - Found and accepted a #4 bar. Location is in harmony with existing improvements. No OCCR was on file for this location.
40. S/4 Corner of Section 8 - Set a #4 bar with "CA 2054" cap. Location was re-established using an east west fence line and set equidistant from opposing section corners. No OCCR was on file for this location.
41. SE Corner of Section 8 - Found and accepted a #4 bar with "PLS 1444" cap. Location is in agreement with OCCR filed in 1988 and is in harmony with existing improvements. The reference monuments were found and verified.

PLS	KH		OKLAHOMA DEPARTMENT OF TRANSPORTATION SURVEY DIVISION SURVEY DATA SHEET
DRAWN	CF,SK		
CHECKED	SS		
APPROVED	KH		
CREW	JH,SA,BH,DR		
SWO 4600 (1) PROJECT NO. 17671(34) SHEET NO. S3			