



NOTES:

USE FIVE (5) DROP LOCATIONS, AS NOTED, TO VERIFY BOTTOM OF HOLE HAS BEEN PROPERLY CLEANED. ADDITIONAL DROPS MAY BE REQUIRED AS DIRECTED BY THE ENGINEER TO VERIFY PROPER CLEANING AND ACCEPTANCE.

SHAFT INSPECTION DEVICE (SID) INSPECTION LOCATIONS



SHAFT INSPECTION DEVICE (SID)



CA-2958
6/30/15

EW-18 OVER BOIS D' ARC CREEK KAY CO.

DESIGN	JTH		OKLAHOMA DEPARTMENT OF TRANSPORTATION
DRAWN	HWL		
CHECKED	JTH		
APPROVED			
SQUAD	CED8 / MKEC		
STATE JOB NO. 28433(04)			SHAFT INSPECTION DEVICE (SID) LOCATIONS
			SHEET NO. B008