

REVISIONS		
REV. NO.	DESCRIPTION	DATE

PAY QUANTITIES					
0200 BRIDGE 'A' - NBI 17506 - US-69 SB OVER US-70					
ITEM		DESCRIPTION		UNIT	QUANTITY
504(C)	1450	EXPANSION DEVICE (BR-1) (2)		LF	97.80
504(G)	6390	RAPID CURE JOINT SEALANT (BR-1) (3)		LF	336.00
504(H)	6389	ELASTOMERIC MORTAR (BR-1) (2)		CF	32.00
509(A)	1326	CLASS AA CONCRETE (BR-1) (3)		CY	30.10
511(B)	6010	EPOXY COATED REINFORCING STEEL (BR-1) (3)		LB	7,770.00
513(B)	6019	CLASS B BRIDGE DECK REPAIR (BR-1) (4)		SY	50.00
513(C)	6020	CLASS C BRIDGE DECK REPAIR (BR-1) (5)		SY	30.00
523(A)	6550	SEALER CRACK PREPARATION (3)		LF	728.00
523(B)	6560	SEALER RESIN (3)		GAL	5.60
535	6130	(SP) CORROSION INHIBITOR (SURFACE APPLIED) (3)(4)(5)		SY	56.00
535	6410	MASTIC ASPHALT JOINT MATERIAL (BR-1) (1)		CF	22.00

PAY QUANTITIES					
0201 BRIDGE 'B' - NBI 17507 - US-69 NB OVER US-70					
ITEM		DESCRIPTION		UNIT	QUANTITY
504(C)	1450	EXPANSION DEVICE (BR-1) (2)		LF	48.90
504(G)	6390	RAPID CURE JOINT SEALANT (BR-1) (3)(6)		LF	385.00
504(H)	6389	ELASTOMERIC MORTAR (BR-1) (2)(6)		CF	32.00
509(A)	1326	CLASS AA CONCRETE (BR-1) (3)		CY	30.10
511(B)	6010	EPOXY COATED REINFORCING STEEL (BR-1) (3)		LB	7,770.00
513(C)	6020	CLASS C BRIDGE DECK REPAIR (BR-1) (5)		SY	45.00
523(A)	6550	SEALER CRACK PREPARATION (3)		LF	728.00
523(B)	6560	SEALER RESIN (3)		GAL	5.60
535	6130	(SP) CORROSION INHIBITOR (SURFACE APPLIED) (3)(5)		SY	56.00
535	6410	MASTIC ASPHALT JOINT MATERIAL (BR-1) (1)		CF	24.00

PAY QUANTITIES					
0202 BRIDGE 'C' - NBI 17534 - US-69 SB OVER W ARKANSAS ST & R.R.					
ITEM		DESCRIPTION		UNIT	QUANTITY
504(C)	1450	EXPANSION DEVICE (BR-1) (2)		LF	81.40
504(G)	6390	RAPID CURE JOINT SEALANT (BR-1) (3)		LF	360.00
504(H)	6389	ELASTOMERIC MORTAR (BR-1) (2)		CF	13.00
509(A)	1326	CLASS AA CONCRETE (BR-1) (3)		CY	32.40
511(B)	6010	EPOXY COATED REINFORCING STEEL (BR-1) (3)		LB	8,370.00
513(B)	6019	CLASS B BRIDGE DECK REPAIR (BR-1) (4)		SY	50.00
523(A)	6550	SEALER CRACK PREPARATION (3)		LF	792.00
523(B)	6560	SEALER RESIN (3)		GAL	6.30
535	6130	(SP) CORROSION INHIBITOR (SURFACE APPLIED) (3)(4)		SY	63.00
535	6410	MASTIC ASPHALT JOINT MATERIAL (BR-1) (1)		CF	10.00

PAY QUANTITIES					
0203 BRIDGE 'D' - NBI 17535 - US-69 NB OVER W ARKANSAS ST & R.R.					
ITEM		DESCRIPTION		UNIT	QUANTITY
504(C)	1450	EXPANSION DEVICE (BR-1) (2)		LF	81.40
504(G)	6390	RAPID CURE JOINT SEALANT (BR-1) (3)		LF	360.00
504(H)	6389	ELASTOMERIC MORTAR (BR-1) (2)		CF	20.00
509(A)	1326	CLASS AA CONCRETE (BR-1) (3)		CY	32.40
511(B)	6010	EPOXY COATED REINFORCING STEEL (BR-1) (3)		LB	8,370.00
513(B)	6019	CLASS B BRIDGE DECK REPAIR (BR-1) (4)		SY	50.00
513(C)	6020	CLASS C BRIDGE DECK REPAIR (BR-1) (5)		SY	45.00
523(A)	6550	SEALER CRACK PREPARATION (3)		LF	792.00
523(B)	6560	SEALER RESIN (3)		GAL	6.30
535	6130	(SP) CORROSION INHIBITOR (SURFACE APPLIED) (3)(4)(5)		SY	63.00
535	6410	MASTIC ASPHALT JOINT MATERIAL (BR-1) (1)		CF	20.00

PAY QUANTITIES					
0204 BRIDGE 'E' - NBI 16591 - US-270 OVER A OK R.R.					
ITEM		DESCRIPTION		UNIT	QUANTITY
504(G)	6390	RAPID CURE JOINT SEALANT (BR-1) (7)		LF	86.00
504(H)	6389	ELASTOMERIC MORTAR (BR-1) (7)		CF	2.00
504(J)	6400	PREFORMED SILICONE FOAM JOINT (BR-1) (8)		LF	76.00
535	6410	MASTIC ASPHALT JOINT MATERIAL (BR-1) (1)		CF	20.00

PAY QUANTITIES					
0640 CONSTRUCTION					
ITEM		DESCRIPTION		UNIT	QUANTITY
641	1399	MOBILIZATION		LSUM	1.00

BR-1:
PAYMENT FOR THIS ITEM WILL BE BASED ON THE PLAN QUANTITY ONLY.
SEE SECTION 109.01B OF THE STANDARD SPECIFICATIONS.

THIS PROJECT IS MANDATORILY TIED WITH 31697(04). THE PRICE BID FOR THIS PROJECT SHALL INCLUDE ALL COSTS OF MOBILIZATION REQUIRED FOR 31697(04) AND 24333(08).

MULTIPLE LOCATIONS	DIVISION TWO	Design	N/A	N/A
GENERAL NOTES AND SUMMARY OF PAY QUANTITIES (SHEET 3 OF 3)(BRIDGE)		Detail	TEE	3/16
		Check	N/A	N/A
		Squad	HENSLY	
		Engr.	DEFRANCO	
STATE OF OKLAHOMA	DEPARTMENT OF TRANSPORTATION	JOB/PIECE NO.	24333(08)	SHEET NO. AB03