

FED. ROAD DIST. NO.	STATE	JOB PIECE NO.	FISCAL YEAR	SHEET NO.	TOTAL SHEETS
6	OKLA.	27050(04)	2017		

DESCRIPTION	REVISIONS	DATE
UPDATED NOTES		10-17-17

MIGRATORY BIRDS

MIGRATORY BIRDS ARE PROTECTED BY THE FEDERAL MIGRATORY BIRD TREATY ACT. MANY BIRDS COMMONLY USE BRIDGES AND CULVERTS FOR NESTING. THE NESTING SEASON FOR MOST MIGRATORY BIRD SPECIES EXTENDS FROM MARCH 1 TO AUGUST 31. MIGRATORY BIRD NESTING USE OF BRIDGE NBI# 19703, NBI# 28135 AND THE CULVERT AT STA. 75+53.13 INVOLVED WITH THIS PROJECT WAS OBSERVED. PAINTING, REPAIR, RETROFIT, REHABILITATION OR DEMOLITION OF THE EXISTING BRIDGE/STRUCTURES SHALL BE CONDUCTED BETWEEN SEPTEMBER 1, AND FEBRUARY 28, WHEN MIGRATORY BIRD NESTS ARE NOT OCCUPIED. IF PAINTING, REPAIR, RETROFIT, REHABILITATION OR DEMOLITION CANNOT BE COMPLETED BETWEEN SEPTEMBER 1 AND FEBRUARY 28, THE BRIDGE SHALL BE PROTECTED FROM NEW NEST ESTABLISHMENT PRIOR TO MARCH 1, BY MEANS THAT DO NOT RESULT IN BIRD DEATH OR INJURY. OPTIONS INCLUDE THE EXCLUSION OF ADULT BIRDS FROM SUITABLE NEST SITES ON OR WITHIN A STRUCTURE BY THE PLACEMENT OF WEATHER-RESISTANT POLYPROPYLENE NETTING WITH 0.25-INCH OR SMALLER OPENINGS, PRIOR TO MARCH 1. METHODS OTHER THAN NETTING MUST BE PRE-APPROVED BY THE ODOT BIOLOGIST.

ALTHOUGH NO NESTS WERE OBSERVED ON ALL OTHER STRUCTURES, THE BIRDS MAY OCCUPY THE STRUCTURES IN THE FUTURE. THE RESIDENT ENGINEER SHALL CONTACT THE ODOT BIOLOGIST AT 405-521-2515 IF ANY BIRD USE OF THE EXISTING STRUCTURES IS OBSERVED. IF BIRDS ARE OBSERVED THEN PAINTING, REPAIR, RETROFIT, REHABILITATION OR DEMOLITION OF THE EXISTING BRIDGE/STRUCTURES SHALL BE CONDUCTED BETWEEN SEPTEMBER 1, AND FEBRUARY 28, WHEN MIGRATORY BIRD NESTS ARE NOT OCCUPIED.

NON- BORROW SITES

LOCATIONS OUTSIDE THE PROJECT AREAS IN THE FOLLOWING AREA MUST NOT BE UTILIZED FOR BORROW, EQUIPMENT STAGING, HAUL ROADS, SPOIL DUMPS OR ANY OFF-SITE PROJECT-RELATED ACTIVITY.

T2N R11W
 SECTION 20 - NE 1/4 NW 1/4 AND NE 1/4 SE 1/4 SW 1/4
 SECTION 19 - SE 1/4 NW 1/4 SE 1/4 (HIGHLAND CEMETERY)
 SECTION 18 - NE 1/4 NW 1/4 NE 1/4
 SE 1/4 NW 1/4 SE 1/4
 (INDIAN AGENCY CEMETERY/COMANCHE MISSION CEMETERY)
 SECTION 17 - SE 1/4 SW 1/4 NE 1/4
 NE 1/4
 NW 1/4 NW 1/4 NW 1/4
 SECTION 16 - NE 1/4 SW 1/4 SW 1/4
 SECTION 7 - SE 1/4 SW 1/4 SE 1/4

LUST SITE

ALIGNMENT/STATION	OCC FAC./CASE NO.	FACILITY
RAMP D, 55+00-58+00, 50' LT	064-3324/16-21780	FORMER EZGO

PETROLEUM CONTAMINATION MAY EXIST AT OR NEAR THE REFERENCED LEAKING UNDERGROUND STORAGE TANK (LUST) SITE. BASED ON THE AVAILABLE INFORMATION, CONTAMINATION IS NOT EXPECTED TO AFFECT CONSTRUCTION ACTIVITIES, BUT IS STILL POSSIBLE. IN THE EVENT CONTAMINATED SOIL OR GROUNDWATER IS ENCOUNTERED, THE CONTRACTOR SHALL ADHERE TO ODOT'S HAZARDOUS MATERIALS SPECIFICATION 107.15 AND NOTIFY THE RESIDENT ENGINEER, WHO MAY THEN CONTACT THE ENVIRONMENTAL PROGRAMS DIVISION AT (405) 521-3026 FOR ASSISTANCE.

DESIGN	AKS	6/12	1-44 & US-62 INTERCHANGE
DRAWN	BWH	6/12	
CHECKED	JES	5/16	
APPROVED			
SQUAD	GARVER		

ENVIRONMENTAL MITIGATION NOTES

STATE JOB NO. 27050(04) SHEET NO. 11