

| FED. ROAD DIST. NO. | STATE | PROJ. NO. | FISCAL YEAR | SHEET NO. | TOTAL SHEETS |
|---------------------|-------|-----------|-------------|-----------|--------------|
| | OKLA. | | | | |

| DESCRIPTION | REVISIONS | DATE |
|-------------|-----------|------|
| | | |

| PT NO. | EASTING | NORTHING | PT NO. | EASTING | NORTHING |
|--------|---------------|--------------|--------|---------------|--------------|
| 7731 | 1734440.50717 | 375465.83813 | 7777 | 1739182.63463 | 369226.73703 |
| 7732 | 1734630.33270 | 375463.97548 | 7778 | 1739194.57668 | 369235.81378 |
| 7733 | 1733066.88362 | 375479.31670 | 7779 | 1739776.25471 | 368668.82316 |
| 7734 | 1735665.74147 | 375453.81562 | 7780 | 1739680.71827 | 368596.20918 |
| 7735 | 1735666.19011 | 375519.81440 | 7781 | 1739955.93370 | 368425.87418 |
| 7736 | 1735311.88951 | 374567.26785 | 7782 | 1739858.52547 | 368355.79111 |
| 7737 | 1735291.98609 | 374552.13994 | 7783 | 1740478.11590 | 367700.09490 |
| 7738 | 1735192.46897 | 374476.50038 | 7784 | 1740510.58531 | 367723.45592 |
| 7739 | 1735212.37240 | 374491.62829 | 7785 | 1740422.38263 | 367572.08794 |
| 7740 | 1735655.45709 | 374073.93004 | 7786 | 1740373.12113 | 367572.06619 |
| 7741 | 1735654.23737 | 373910.27735 | 7787 | 1740619.42864 | 367572.17495 |
| 7742 | 1735958.25077 | 373675.55180 | 7788 | 1740845.88314 | 367257.42661 |
| 7743 | 1735978.15420 | 373690.67971 | 7789 | 1740845.94942 | 367214.52815 |
| 7744 | 1736099.17749 | 373531.45232 | 7790 | 1740846.41340 | 366914.23887 |
| 7745 | 1736079.27407 | 373516.32441 | 7791 | 1740846.34711 | 366957.13734 |
| 7746 | 1736461.78772 | 372847.80312 | 7792 | 1741243.87464 | 366404.61518 |
| 7747 | 1736449.11761 | 372847.94713 | 7793 | 1741264.16802 | 366419.21582 |
| 7748 | 1736588.48884 | 372846.36299 | 7794 | 1741365.63492 | 366492.21902 |
| 7749 | 1736715.18996 | 372844.92287 | 7795 | 1741345.34154 | 366477.61838 |
| 7750 | 1737125.02046 | 372304.40323 | 7796 | 1742425.93765 | 364975.70149 |
| 7751 | 1737054.36813 | 372249.94274 | 7797 | 1742301.31746 | 364977.68531 |
| 7752 | 1737719.62143 | 371374.68525 | 7798 | 1742349.35926 | 364910.91217 |
| 7753 | 1737751.46691 | 371398.88991 | 7799 | 1742536.28955 | 364907.93645 |
| 7754 | 1737624.08500 | 371302.07127 | 7800 | 1740849.36985 | 365000.79873 |
| 7755 | 1737592.23952 | 371277.86661 | 7801 | 1740849.16474 | 364934.79363 |
| 7756 | 1738219.34206 | 370783.31801 | 7802 | 1743417.84479 | 364959.91142 |
| 7757 | 1738213.43622 | 370460.57331 | 7803 | 1743417.80972 | 364893.90361 |
| 7758 | 1738209.09061 | 370223.09247 | 7804 | 1743195.14553 | 363992.19475 |
| 7759 | 1738277.89540 | 370375.76595 | 7805 | 1743162.67612 | 363968.83373 |
| 7760 | 1738394.14101 | 370222.82443 | 7806 | 1743414.19326 | 363619.25090 |
| 7761 | 1738275.09651 | 370222.81138 | 7807 | 1743413.66098 | 363431.64281 |
| 7762 | 1738283.80124 | 370698.51065 | 7808 | 1743410.41354 | 362287.05517 |
| 7763 | 1738256.74634 | 372827.40107 | 7809 | 1738208.43247 | 370157.09570 |
| 7764 | 1738322.75199 | 372827.10627 | 7810 | 1735626.92494 | 370245.68911 |
| 7765 | 1738645.33315 | 370222.85197 | 7811 | 1735626.44371 | 370179.69080 |
| 7766 | 1738318.70511 | 370156.81616 | 7812 | 1737081.40758 | 370232.96087 |
| 7767 | 1738274.43209 | 370156.81131 | 7813 | 1736895.26471 | 370234.58981 |
| 7768 | 1738508.72989 | 369906.80521 | 7814 | 1738204.12129 | 367571.32365 |
| 7769 | 1738608.24701 | 369982.44477 | 7815 | 1738270.12107 | 367571.13757 |
| 7770 | 1738695.49331 | 370156.85746 | 8000 | 1717419.50507 | 394490.22116 |
| 7771 | 1738638.38160 | 369968.86284 | 8001 | 1718344.91900 | 394478.87748 |
| 7772 | 1738818.47818 | 369953.73493 | 8002 | 1718734.54376 | 394652.97399 |
| 7773 | 1740841.76765 | 370223.09272 | 8003 | 1719390.93761 | 394647.41230 |
| 7774 | 1740841.40286 | 370157.09268 | 8004 | 1719388.50445 | 393992.58218 |
| 7775 | 1739302.05517 | 369317.50450 | 8005 | 1721315.39208 | 388782.40032 |
| 7776 | 1739250.11312 | 369308.42776 | 8006 | 1721278.01550 | 386132.16450 |

| PT NO. | EASTING | NORTHING | PT NO. | EASTING | NORTHING |
|--------|---------------|--------------|--------|---------------|--------------|
| 8007 | 1722648.07461 | 390612.79458 | 9028 | 1730519.82450 | 391302.67100 |
| 8008 | 1723140.84640 | 390098.93043 | 9029 | 1731834.48475 | 391294.58750 |
| 8009 | 1723678.73478 | 389538.01854 | 9030 | 1733149.14500 | 391286.50400 |
| 8010 | 1723440.55247 | 389309.61280 | 9031 | 1717387.87210 | 390063.76347 |
| 8011 | 1725243.96240 | 387448.01169 | 9032 | 1718708.40368 | 390074.25437 |
| 8012 | 1722606.91600 | 387475.74300 | 9033 | 1720018.18076 | 390084.65983 |
| 8013 | 1729155.07978 | 382137.19241 | 9034 | 1721330.38063 | 390095.08453 |
| 8014 | 1727854.45050 | 382160.22550 | 9035 | 1722642.57079 | 390105.50916 |
| 8015 | 1730478.88655 | 382113.74887 | 9036 | 1723952.73714 | 390088.21104 |
| 8016 | 1729145.91927 | 380823.79642 | 9037 | 1725262.90349 | 390070.91293 |
| 8017 | 1734364.75942 | 378125.66625 | 9038 | 1726578.86370 | 390053.53832 |
| 8018 | 1734350.04221 | 375499.72740 | 9039 | 1727894.82391 | 390036.16371 |
| 8019 | 1736968.06638 | 372842.04860 | 9040 | 1729202.07558 | 390019.38336 |
| 8020 | 1736981.83321 | 375474.04390 | 9041 | 1730509.32726 | 390002.60300 |
| 8021 | 1737081.11881 | 370199.96213 | 9042 | 1731822.66519 | 389985.74452 |
| 8022 | 1737085.21414 | 370667.94421 | 9043 | 1733136.00311 | 389968.88604 |
| 8023 | 1736899.07127 | 370669.57316 | 9044 | 1717383.26407 | 388742.27945 |
| 8024 | 1736894.97594 | 370201.59108 | 9045 | 1718692.46357 | 388755.63767 |
| 9000 | 1712202.22100 | 396692.74600 | 9046 | 1720002.42316 | 388769.00364 |
| 9001 | 1714823.92428 | 396659.06091 | 9047 | 1722628.36100 | 388795.79700 |
| 9002 | 1717445.67600 | 396625.23700 | 9048 | 1725253.43080 | 388759.16539 |
| 9003 | 1718740.80920 | 396616.39234 | 9049 | 1727892.31500 | 388722.34100 |
| 9004 | 1720055.66500 | 396607.41300 | 9050 | 1730498.71721 | 388688.56268 |
| 9005 | 1722685.32243 | 396589.40391 | 9051 | 1733122.89400 | 388654.55400 |
| 9006 | 1717429.64972 | 395317.81850 | 9052 | 1717374.76403 | 387432.58322 |
| 9007 | 1718736.63224 | 395307.44677 | 9053 | 1718676.50775 | 387435.72208 |
| 9008 | 1712180.61600 | 394053.63600 | 9054 | 1717366.26400 | 386122.88700 |
| 9009 | 1714799.77217 | 394031.99608 | 9055 | 1718660.55193 | 386115.80650 |
| 9010 | 1717413.62345 | 394010.39999 | 9056 | 1719970.56000 | 386108.64000 |
| 9011 | 1718732.45528 | 393998.50120 | 9057 | 1722585.47100 | 386155.68900 |
| 9012 | 1720044.55363 | 393986.66315 | 9058 | 1725234.49400 | 386136.85800 |
| 9013 | 1722670.64200 | 393962.97000 | 9059 | 1727887.27000 | 386094.74000 |
| 9014 | 1717403.05179 | 392697.82372 | 9060 | 1730477.48795 | 386059.34913 |
| 9015 | 1718728.26142 | 392684.26051 | 9061 | 1733096.26600 | 386026.03400 |
| 9016 | 1712159.08000 | 391427.55400 | 9062 | 1722574.35600 | 383524.05600 |
| 9017 | 1714775.75994 | 391420.14670 | 9063 | 1725218.89783 | 383497.97072 |
| 9018 | 1717392.48013 | 391385.24744 | 9064 | 1727865.51100 | 383471.86500 |
| 9019 | 1718724.06756 | 391370.01981 | 9065 | 1730478.41961 | 383431.05738 |
| 9020 | 1720093.39618 | 391355.04673 | 9066 | 1733078.37900 | 383390.45200 |
| 9021 | 1721344.66209 | 391345.84287 | 9067 | 1722563.33800 | 380892.43900 |
| 9022 | 1722655.92800 | 391336.63900 | 9068 | 1725203.39906 | 380875.56325 |
| 9023 | 1723963.92710 | 391328.49451 | 9069 | 1727843.39000 | 380848.58600 |
| 9024 | 1725271.92620 | 391320.35002 | 9070 | 1730479.35280 | 380798.41869 |
| 9025 | 1726584.58560 | 391312.17651 | 9071 | 1733060.51700 | 380755.16800 |
| 9026 | 1727897.24500 | 391304.00300 | 9072 | 1735698.30300 | 380747.77000 |
| 9027 | 1729208.53475 | 391303.33700 | 9073 | 1738336.16200 | 380740.32800 |

| PT NO. | EASTING | NORTHING | PT NO. | EASTING | NORTHING |
|--------|---------------|--------------|--------|---------|----------|
| 9074 | 1727832.70400 | 378209.25100 | | | |
| 9075 | 1730448.39042 | 378171.47338 | | | |
| 9076 | 1733047.37300 | 378133.93700 | | | |
| 9077 | 1735682.14584 | 378117.39550 | | | |
| 9078 | 1738316.91800 | 378100.85400 | | | |
| 9079 | 1727817.62400 | 375560.94000 | | | |
| 9080 | 1730417.27601 | 375531.63023 | | | |
| 9081 | 1733034.09700 | 375512.64000 | | | |
| 9082 | 1735665.98741 | 375486.81480 | | | |
| 9083 | 1738297.67900 | 375461.27300 | | | |
| 9084 | 1740907.86700 | 375469.29600 | | | |
| 9085 | 1743518.07034 | 375477.41169 | | | |
| 9086 | 1733017.23000 | 372886.95500 | | | |
| 9087 | 1735646.38775 | 372857.07120 | | | |
| 9088 | 1738289.74500 | 372827.02600 | | | |
| 9089 | 1740874.65502 | 372833.31264 | | | |
| 9090 | 1743506.73400 | 372839.71400 | | | |
| 9091 | 1732994.00600 | 370243.31800 | | | |
| 9092 | 1735626.67900 | 370212.69000 | | | |
| 9093 | 1738241.48706 | 370189.80770 | | | |
| 9094 | 1740841.35187 | 370190.09267 | | | |
| 9095 | 1743475.90244 | 370203.33878 | | | |
| 9096 | 1732974.66800 | 367603.12100 | | | |
| 9097 | 1735607.95784 | 367587.10945 | | | |
| 9098 | 1738237.12100 | 367571.12300 | | | |
| 9099 | 1740845.39666 | 367572.27473 | | | |
| 9100 | 1743446.38912 | 367573.42325 | | | |
| 9101 | 1732955.05159 | 364962.87875 | | | |
| 9102 | 1735589.19522 | 364955.71224 | | | |
| 9103 | 1738212.28254 | 364951.56916 | | | |
| 9104 | 1740849.42085 | 364967.79373 | | | |
| 9105 | 1743450.90200 | 364926.38100 | | | |
| 9106 | 1738199.22663 | 362324.50910 | | | |
| 9107 | 1740828.76025 | 362305.61007 | | | |
| 9108 | 1743443.41300 | 362286.81800 | | | |
| 9109 | 1738180.83200 | 359681.64700 | | | |
| 9110 | 1740808.26200 | 359664.34600 | | | |
| 9111 | 1743435.71800 | 359646.87400 | | | |

| | | | |
|---|-------------|--|--|
| PLS | KH | | OKLAHOMA DEPARTMENT OF TRANSPORTATION SURVEY DIVISION |
| DRAWN | CF,SK | | |
| CHECKED | SS | | |
| APPROVED | KH | | |
| CREW | JH,SA,BH,DR | | |
| SWO 4600 (1) PROJECT NO. 17671(34) SHEET NO. S9 | | | |