OKLAHOMA DEPARTMENT OF TRANSPORTATION FED. ROAD DIST. NO. STATE PROJ. NO. FISCAL SHEET TOTAL YEAR NO. SHEETS OKLA.

1/4 SECTION CORNER — Found and accepted a No. 3 Bar with cap stamped "JR PLS 1614" at location. No previous corner record was filed for this location.


SECTION CORNER — Found and accepted a BLM Brass Monument recently established by a cadastral surveyor of the Bureau of Land Management. A corner record was filed for this location, however, no references were found.

S Face of

SECTION CORNER — Found and accepted a No. 3 Bar at location. Location fits previously filed reference.

1/4 SECTION CORNER — Found and accepted a BLM Brass Monument recently established by a cadastral surveyor of the Bureau of Land Management. No previous corner references were found that matched the accepted location.

SECTION CORNER — Found and accepted a BLM Brass Monument recently established by a cadastral surveyor of the Bureau of Land Management. Location fits previously filed reference. Also found 2 references from a previously filed corner record.



Center of 5" Steel Post

S41°42'47"E

76.48

SW04564(1)

SECTION CORNER — Found and accepted a Brass monument at location. Monument surface is not readable but parts of it appear to read "ODOT".

CREW PT.JF.CF.SA

DRAWN CHECKED

OKLAHOMA DEPARTMENT OF TRANSPORTATION SURVEY DATA SHEET APPROVED

NOTE: REFERENCE'S SHOWN ARE NOT TO SCALE

SDS 10 OF 13

SCALE:

1" = 500'